


www.evotech-performance.com Suzuki V-Strom 1050 SP Connect Sat Nav Mount Instruction



For SP Connect mirco stem mount alu Part number #53122 follow instructions 1 - 16

For SP Connect anti vibration module Part number #53135 follow instructions 17 - 31











































HH









 $\cap$ 









































































III H











































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced





www.evotech-performance.com