




www.evotech-performance.com Suzuki V-Strom 650 Ultimateaddons Sat Nav Mount






















///























Q










Κ Repeat **Both Sides**























O

SIG

9

3



It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced





www.evotech-performance.com